

Exploded view diagram of a 12-plate hydraulic press. The components are numbered as follows:

- 1: Top plate
- 2: Bolt
- 3: Nut
- 4: Plate
- 5: Plate
- 6: Plate
- 7: Bottom plate
- 8: O-ring
- 9: Bolt
- 10: Nut
- 11: Spring
- 12: Bolt



PDF-1010200F